



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
March 29, 2011

Reviewed: 

Mine Name: January Mine Dump	Permit Number: S/023/0100
Operator Name: Northstar Clay Mines Inc.	Inspection Date: March 24, 2011
Inspector(s): Wayne Western	Time: 9:30 – 9:50 AM
Other Participants: none	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond amount is \$5,900.00 and the bond renewal date is May 12, 2011. The Division should notify the Permittee that the bond is due for adjustment.

The site is close to a public road. No public safety issues were observed.

Snow covered part of the site.

Conclusions and Recommendations:

The Division should inspect the site on a regular basis.

Inspection Date: March 24, 2011

Page 2 of 44

S/023/0100


Inspector's Signature

WHW

cc: (OPERATOR)

Jerry_Mansfield@BLM.gov


O:\M023-Juab\S0230100-JanuaryMineDump\inspections\Insp-03242011.doc



Pit looking east



Pit looking north



Excavated material on site



Edge of disturbed area.